









Alenia Module 3135-08


Looking down on backside of sensor




- Chips 0, 1, 2 and part of 3 show uneven pressure - more outside edge, less middle
- In general other chips look pretty good, although there is some variation of pressure as can be seen in photos.









11a



14a



15a



14b